#### **ENVIRONMENTAL CHEMISTS**

# Analysis For Total Metals By EPA Method 200.8

Client ID: M03416 Alaskan Copper Works Client: Date Received: 12/09/08 Project: PO M03416, F&BI 812095 12/10/08 Lab ID: 812095-01 x10 Date Extracted: 12/11/08 Data File: 812095-01 x10.035 Date Analyzed: Matrix: Water Instrument: ICPMS1

Matrix: Water Instrument: ICPMS
Units: ug/L (ppb) Operator: hr

Lower Upper Internal Standard: % Recovery: Limit: Limit:

Germanium 101 60 125

Concentration
Analyte: ug/L (ppb)

 Chromium
 1,480

 Nickel
 2,040

 Copper
 1,140

 Zinc
 67.6

# ENVIRONMENTAL CHEMISTS

# Analysis For Total Metals By EPA Method 200.8

Client ID:	Method Blank	Client:	Alaskan Copper Works
Date Received:	Not Applicable	Project:	PO M03416, F&BI 812095
Date Extracted:	12/10/08	Lab ID:	I8-468 mb
Date Analyzed:	12/11/08	Data File:	I8-468 mb.023
Matrix:	Water	Instrument:	ICPMS1
Units:	ug/L (ppb)	Operator:	hr

		Lower	Upper
Internal Standard:	% Recovery:	Limit:	Limit:
Germanium	25 Bu - 2010 111 - 14 2 15	60	125
Indium	113	60	125
Holmium	110	60	125

	Concentration
Analyte:	ug/L (ppb)
Chromium	<1
Nickel	<1
Copper	<1
Zinc	<2

#### **ENVIRONMENTAL CHEMISTS**

Date of Report: 12/15/08 Date Received: 12/09/08

Project: Metro Self Monitor, PO M03416, F&BI 812095

# QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 812077-01 (Duplicate)

Analyte	Reporting Units	Sample Result	Duplicate Result	Relative Percent Difference	Acceptance Criteria
Chromium	ug/L (ppb)	1.55	1.53		0-20
Nickel	ug/L (ppb)	6.39	6.60	3	0-20
Copper	ug/L (ppb)	241	250	4	0-20
Zinc	ug/L (ppb)	845	863	2	0-20

Laboratory Code: 812077-01 (Matrix Spike)

Analyte	Reporting Units	Spike Level	Sample Result	Percent Recovery MS	Acceptance Criteria
Chromium	ug/L (ppb)	20	1.55	98	50-150
Nickel	ug/L (ppb)	20	6.39	91 b	50-150
Copper	ug/L (ppb)	20	241	129 b	50-150
Zinc	ug/L (ppb)	50	845	142 b	50-150

Laboratory Code: Laboratory Control Sample

Analyte	Reporting Units	Spike Level	Percent Recovery LCS	Acceptance Criteria
Chromium	ug/L (ppb)	20	102	70-130
Nickel	ug/L (ppb)	20	98	70-130
Copper	ug/L (ppb)	20	96	70-130
Zinc	ug/L (ppb)	50	88	70-130

#### **ENVIRONMENTAL CHEMISTS**

# **Data Qualifiers & Definitions**

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probablility.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- ${
  m jl}$  The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

#### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com



December 15, 2008

#### **INVOICE #08ACU1215-1**

Accounts Payable Alaskan Copper Works 628 South Hanford Seattle, WA 98134

RE: Project Metro Self Monitor, PO M03416, F&BI 812095 - Results of testing requested by Gerry Thompson for material submitted on December 9, 2008.

FEDERAL TAX ID #(b) (6)

Par (1961) 268-6844	Ph. (206) 285-8282	8082 18th Avanus West	Prizedoma & Bruga, Inc.										Mosylo	Sample ID		Phone # 201-305 74 206 382-4308	Car, Man, Mr SEATTLE	Address 628 ST	Send Report To Scale
Reconvert by:	Moreover of the Control of the Contr	Bearinguis food to		•		74							0/	Lab ID		7033 # Z	To us	700	7
	a	P											12/28	Date		06 382-	2842	at so	honos
	aus												QC.1	Time		308		9/2	***
	5	() ()											(Jet)	Sample Type		Guab	REMARKS	Metro Sel	to the state of th
-	han	genela	BRINT NAME	Alexander and the second	Service	No. in the contract of								# of containers				Self	
1	3	1	NA					-						TPH-Diesel	$\prod$		* .		
	han	Longs	闰		<u> </u>		<u> </u>	╂	+			-		TPH-Gasoline BTEX by 8021B	$\  \ $			montain	
		Ĺ				e de	-	1	+					VOCs by 8260	11			\$	
_	_													SVOCs by 8270	A			2	V
													,	HFS	EXE			1034	
	67	12	8		: 				<b>_</b>		ļ	ļ	$\times$	CeCy NEZ	ANALYSES REQUESTED		. ¥	WO3411	
	81	5	OMPANY	······································			ļ		4	ļ		<u> </u>			- E			0,	
	'		3	edra dag		-		<u> </u>	ļ		<u> </u>				1180	00		720	3.
								<u> </u>								Will c		Chandard C Rush charges:	
-	E	10		*****	المعارضة المعارفة				<u> </u>		- none in			Name of the last o		W I's	S AND	2	引
	10	8%	DATE													sordar	SAMPLE DISPOSAL  Dispose after 30 days	O Standard (2 Weeks)  XRUSH	CHAROUND THANK
+	0.8	<u> </u>								1	1	1.		Notes		strae	dy	Weeks)	
	3:36	2,500	TOMB											8		□ Roturn samples □ Will call with instructions	- AL	d by:	
	0	3	<b>B</b>	. 1						1				,		1			

#### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

December 15, 2008

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on December 9, 2008 from the Metro Self Monitor, PO M03416, F&BI 812095 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you should have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU1215R.DOC